BDC Status

- BDC had been seriously damaged during spring shutdown as the north-hall-staff was pulling it out of the cryostat
  $\longrightarrow$ several large gas leaks at inner radius!
- Recovery after subsequent repair went very smoothly! (air-tightness better than before the accident!)



- \- in August, one half-sector had to be disconnected
  \- now 4 half-sectors out of 128 dead
  \- still at least 7 out of 8 layers active everywhere in θ, ϕ!

BDC Efficiency



- Total BDC Efficiency is 98% !

Summary: BDC is running smoothly and efficiently!